TECH LIGHT

20W Rechargeable LED Work Light
User Manual
SL-2859

Box Contents:

1 x 20W Rechargeable LED Work Light
1 x USB Charging Cable
1 x USB Mains Power Adaptor

Product Diagram:

Rubberised Housing

LED

Acrylic Glass

360° Adjustable Bracket

USB Charging Port

DC Power Socket

Battery Level Indicator

Power/Mode Button

Screw Mount

Charging:

1. Connect the USB cable provided to the DC power socket on the rear of the work light.
2. Connect the USB plug to the USB mains power adaptor or a USB charging port on a computer.
3. Charging will take between 4 and 10 hours depending on if you're using the 5VDC, 2A power supply included or a computer USB port which is only 500mA.
4. The battery level indicator will have all 4 LEDS displayed when fully charged, you can now disconnect the USB charging cable.

Modes:

Press the power/mode button to use each of the modes on the work light.

1. Battery Level Indicator
2. High
3. Medium
4. Low
5. Flashing
6. Off

Safety:

1. Place the LED work light in a well ventilated area and keep a distance of at least 0.5m if placed near a wall.
2. Do not open the equipment or touch any of its internal parts.
3. Do not expose the charging input socket or cable to water or any other liquids.

Specifications:

LED: 20W COB
LED Colour: Cool White
Lumens: 1800
Burn Time: 3hrs (High)
        6hrs (Medium)
        9hrs (Low)
        3hrs (Flashing)

Charging Time: 4hrs @ 2A
Charging Input: 5VDC, 2A
Battery: Li-Ion 3.7V, 6600mAh
USB Charging Port: 5VDC, 1A
IP Rating: IP65
Protection: Charge & Discharge
Dimensions: 260 (W)x173 (H)x120 (D)mm