

User Manual

Wireless 5KG Scales With Backlit LCD

QM-7289



Distributed by: TechBrands by Electus Distribution Pty. Ltd. 320 Victoria Rd, Rydalmere NSW 2116 Australia

Ph: 1300 738 555 Int'l: +61 2 8832 3200 Fax: 1300 738 500 www.techbrands.com

Specifications:

Capacity: 5KG
Units: g/lb/oz
Resolution: 1g/0.1oz


Batteries: Scales: 2 x AAA (not included)

Display: 3 x AAA (not included)

Dimensions: Scales: 220(L) x 165(W) x 19(H)mm

Display: 130(L) x 82(W) x 25(D)mm

Product Diagram:



- 1. Power / TARE
- 2. Backlit LCD
- 3. Magnetic Mounts
- 4. Kick Stand

Instructions:

Overview:

- Open the battery compartment and place 2 x AAA batteries in the scales, and 3 x AAA batteries in the display unit. Ensure to insert in the correct polarity as marked.
- Touch the POWER button to turn on the unit. It will display "1888", then show "0" g/lb/oz.
- The scales are now ready to use.
- Press and hold the POWER button for 2 seconds to turn the unit off. The unit will also turn off automatically after 20 seconds of inactivity.

Setting the display unit (buttons located at the rear of the unit):

- Press and hold down the SET button for 2 seconds (when using it for the first time the unit will enter this mode automatically when the batteries are inserted), lb/oz/g will be flashing on the screen.
- Press the UP or DOWN buttons to set the unit of weight measure.
- Press the SET button and the °F or °C will be flashing on the screen.
- Press the UP or DOWN buttons to set the unit of temperature measure.
- Press the SET button and the '24h' or '12h' will be flashing on the screen.
- Press the UP or DOWN buttons to set 12 or 24 hour time.
- Press the SET button and the hour will be flashing on the screen.
- Press the UP or DOWN buttons to set the hour.
- Press the SET button and the minutes will be flashing on the screen.
- Press the UP or DOWN buttons to set the minute.
- Press the SET button to lock in the settings.

Using the scales:

- Place the scales on a flat surface, and have the display unit within 2m range.
- Turn the scales on using the POWER button.
- Place the item to weigh on the scales.

How to use TARE function:

- To calculate the net weight, touch the TARE button to set back to 0g/lb/oz between each mass added to the scales.

NOTE:

- When the LCD display becomes dimmer, please replace the batteries.
- Only use AAA batteries in these scales and display unit.
- Ensure not to mix old and new batteries.
- Please dispose of used batteries in a responsible manner.
- Never attempt to open, modify or repair the scales or display unit in any way.
- Do not drop heavy things onto the scales, or drop items from a height onto the scales as it may damage the unit.